

MSPM0G351x, MSPM0G151x, MSPM0G351x-Q1 Microcontrollers



ABSTRACT

This document describes the known exceptions to the functional specifications (advisories).

Table of Contents

1 Functional Advisories	1
2 Preprogrammed Software Advisories	2
3 Debug Only Advisories	2
4 Fixed by Compiler Advisories	3
5 Device Nomenclature	3
5.1 Device Symbolization and Revision Identification.....	3
6 Advisory Descriptions	5
7 Trademarks	24
8 Revision History	24

1 Functional Advisories

Advisories that affect the device operation, function, or parametrics.

✓ The check mark indicates that the issue is present in the specified revision.

Errata Number	Rev A (Prototype X-Marked Products)	Rev C
ADC_ERR_06	✓	✓
ADC_ERR_10	✓	✓
AES_ERR_01	✓	✓
CPU_ERR_02	✓	✓
CPU_ERR_03	✓	✓
FLASH_ERR_01	✓	✓
FLASH_ERR_03	✓	✓
FLASH_ERR_04	✓	✓
FLASH_ERR_05	✓	✓
FLASH_ERR_08	✓	✓
GPIO_ERR_04	✓	✓
I2C_ERR_04	✓	✓
I2C_ERR_05	✓	✓
I2C_ERR_06	✓	✓
I2C_ERR_07	✓	✓
I2C_ERR_08	✓	✓
I2C_ERR_09	✓	✓
I2C_ERR_10	✓	✓

Errata Number	Rev A (Prototype X-Marked Products)	Rev C
I2C_ERR_13	✓	✓
KEYSTORE_ERR_01	✓	✓
MATHACL_ERR_01	✓	✓
MATHACL_ERR_02	✓	✓
PMCU_ERR_09	✓	✓
PMCU_ERR_10	✓	
PMCU_ERR_11	✓	✓
RST_ERR_01	✓	✓
RTC_ERR_01	✓	✓
SPI_ERR_02	✓	✓
SPI_ERR_04	✓	✓
SPI_ERR_05	✓	✓
SPI_ERR_06	✓	✓
SPI_ERR_07	✓	✓
SRAM_ERR_03	✓	
SYSCTL_ERR_01	✓	✓
SYSCTL_ERR_02	✓	✓
SYSCTL_ERR_03	✓	✓
SYSCTL_ERR_04	✓	✓
SYSOSC_ERR_01	✓	✓
SYSOSC_ERR_02	✓	✓
SYSPLL_ERR_01	✓	✓
TIMER_ERR_04	✓	✓
TIMER_ERR_06	✓	✓
TIMER_ERR_07	✓	✓
UART_ERR_01	✓	✓
UART_ERR_02	✓	✓
UART_ERR_04	✓	✓
UART_ERR_05	✓	✓
UART_ERR_06	✓	✓
UART_ERR_07	✓	✓
UART_ERR_08	✓	✓
UART_ERR_10	✓	✓
UART_ERR_11	✓	✓

2 Preprogrammed Software Advisories

Advisories that affect factory-programmed software.

✓ The check mark indicates that the issue is present in the specified revision.

3 Debug Only Advisories

Advisories that affect only debug operation.

✓ The check mark indicates that the issue is present in the specified revision.

Errata Number	Rev A	Rev B
GPIO_ERR_03	✓	✓

4 Fixed by Compiler Advisories

Advisories that are resolved by compiler workaround. Refer to each advisory for the IDE and compiler versions with a workaround.

✓ The check mark indicates that the issue is present in the specified revision.

5 Device Nomenclature

To designate the stages in the product development cycle, TI assigns prefixes to the part numbers of all MSP MCU devices. Each MSP MCU commercial family member has one of two prefixes: MSP or XMS. These prefixes represent evolutionary stages of product development from engineering prototypes (XMS) through fully qualified production devices (MSP).

XMS – Experimental device that is not necessarily representative of the final device's electrical specifications

MSP – Fully qualified production device

Support tool naming prefixes:

X: Development-support product that has not yet completed Texas Instruments internal qualification testing.

null: Fully-qualified development-support product.

XMS devices and X development-support tools are shipped against the following disclaimer:

"Developmental product is intended for internal evaluation purposes."

MSP devices have been characterized fully, and the quality and reliability of the device have been demonstrated fully. TI's standard warranty applies.

Predictions show that prototype devices (XMS) have a greater failure rate than the standard production devices. TI recommends that these devices not be used in any production system because their expected end-use failure rate still is undefined. Only qualified production devices are to be used.

TI device nomenclature also includes a suffix with the device family name. This suffix indicates the temperature range, package type, and distribution format.

5.1 Device Symbolization and Revision Identification

The package diagrams below indicate the package symbolization scheme, and [Table 5-1](#) defines the device revision to version ID mapping.




Figure 5-1. Package Symbolization

Table 5-1. Die Revisions

Revision Letter	Version (in the device factory constants memory)
A	1

Table 5-1. Die Revisions (continued)

Revision Letter	Version (in the device factory constants memory)
C	2

The revision letter indicates the product hardware revision. Advisories in this document are marked as applicable or not applicable for a given device based on the revision letter. This letter maps to an integer stored in the memory of the device, which can be used to look up the revision using application software or a connected debug probe.

6 Advisory Descriptions

ADC_ERR_06	ADC Module
Category	Functional
Function	ADC Output code jumps degrading DNL/INL specification
Description	When a conversion error occurs, the error will be a fixed +/- 64LSB jump in the digital output code of the ADC without a corresponding change in the ADC input voltage. At worst case scenario, -40C, the error rate is 1 in 24M converted samples in 12-bit mode. (VDD voltage and reference used has no impact on errata rate)
Workaround	Depending on the application needs the best workaround may vary, but the following workarounds in software are proposed. Selection of the best workaround is left to the judgment of the system designer. Workaround 1: Upon ADC result outside of application threshold (via ADC Window Comparator or software thresholding), trigger or wait for another ADC result before making critical system decisions Workaround 2: During post-processing, discard ADC values which are sufficiently far from the median or expected value. The expected value should be based on the average of real samples taken in the system, and the threshold for rejection should be based on the magnitude of the measured system noise. Workaround 3: Use ADC sample averaging to minimize the effect of the results of any single incorrect conversion.
ADC_ERR_10	ADC Module
Category	Functional
Function	ADCMEMRES swap is seen when PA15 is toggling
Description	Set up condition: 1. ADC is in repeat sequence mode 2. ADC can use any sequence of channels to read data 3. PA15 is toggling by either an external device or the MCU itself (such as I2C or PWM). Observation: When the software is starting the ADC conversion, sometimes MEMRES data will swap. The data which needs to be in MEMRES0 is coming into MEMRES1, MEMRES1 data is coming into MEMRES2..so on. In repeat mode, when this errata happens, the last MEMRES will appear in MEMRES0.

ADC_ERR_10
(continued)

ADC Module

The toggling signal on PA15 can affect the conversion clock of the ADC. Which causes the ADC to store the previous result before the correct channel data comes.

Workaround

Avoid fast switching signals (12kHz or faster) on PA15.

AES_ERR_01
AES Module

Category

Functional

Function

AES Saved Context Ready interrupt is not generating as expected

Description

Saved Context Ready interrupt is not getting generated. The interrupt is generated if an access (read or write) is made to any AES register.

Workaround

Use polling based mechanism to check the status bit for Saved Context Ready in CTRL register instead of interrupt.

CPU_ERR_02
CPU Module

Category

Functional

Function

Limitation of disabling prefetch for CPUSS

Description

CPU prefetch disable will not take effect if there is a pending flash memory access.

Workaround

Disable the prefetcher, then issue a memory access to the shutdown memory (SHUTDNSTORE) in SYSCTL, this can be done with
SYSCTL.SOCLOCK.SHUTDNSTORE0;

After the memory access completes the prefetcher will be disabled.

Example:

```
CPUSS.CTL.PREFETCH = 0x0; //disables prefetcher
```

```
SYSCTL.SOCLOCK.SHUTDNSTORE0; // memory access to shutdown memory
```

CPU_ERR_03
CPU Module

Category

Functional

Function

Prefetcher can fetch wrong instructions when transitioning into Low power modes

CPU_ERR_03

(continued)

CPU Module

Description

When transitioning into low power modes and there is a pending prefetch, the prefetcher can erroneously fetch incorrect data (all 0's). When the device wakes up, if the prefetcher and cache do not get overwritten by ISR code, then the main code execution from flash can get corrupted. For example, if the ISR is in the SRAM, then the incorrect data that was prefetched from Flash does not get overwritten. When the ISR returns the corrupted data in the prefetcher can be fetched by the CPU resulting in incorrect instructions. A HW Event wake is another example of a process that will wake the device, but not flush the prefetcher.

Workaround

Disable prefetcher before entering low power modes.

Example:

```
CPUSS.CTL.PREFETCH = 0x0; // disables prefetcher
SYSCTL.SOCLOCK.SHUTDNSTORE0 // Read from SHUTDOWN Memory
__WFI(); // or __WFE(); this function calls the transition into low power mode
CPUSS.CTL.PREFETCH = 0x1; // enables prefetcher
```

FLASH_ERR_01

FLASH Module

Category

Functional

Function

Access to FACTORY region will lead to hard fault with flash wait state equal to 2.

Description

Access to FACTORY region when the flash wait state is set to 2 will trigger a hard fault. When MCLK is set to beyond 32MHz, the flash wait states needs to be 2.

Workaround

Set MCLK at a lower frequency(with flash wait state as 0 or 1) to access FACTORY region. Access the FACTORY region while the flash wait states is less than 2 (requires MCLK to be 32MHz or less). Cache the data in SRAM, MAIN flash, or DATA flash, if the application needs to access these values during run time. A typical value would be the Temperature Sensor's calibration value.

FLASH_ERR_03

FLASH Module

Category

Functional

Function

Flash access with 2 wait states followed by invalid bootcode access will cause next flash access to also throw a violation

Description

Doing a Flash access followed by a access to BOOTCODE when you have 2 wait states will cause the next flash access to also cause a violation.

Workaround

Do not attempt to access boot-code region post-boot phase. Otherwise, there will need to be 4 clock cycles in between the bootcode violation and next correct flash access.

FLASH_ERR_04 *FLASH Module*

Category

Functional

Function

Wrong Address will get reported in the SYSCTL_DEDERRADDR if the error is in the NONMAIN or Factory region

Description

When a FLASHDED error appears the data will truncate the most significant byte. In the memory limits of the device, the most significant byte does not have an impact to the return address for MAIN flash. For NONMAIN flash or Factory region the MSB should be listed as 0x41xx.xxxx

Workaround

If the return address of the SYSCTL_DEDERRADDR returns a 0x00Cxxxxx, do an OR operation with 0x41000000 to get the proper address for the NONMAIN or Factory region return address. For example, if SYSCTL_DEDERRADDR = 0x00C4013C, the real address would be 0x41C4013C.

For MAIN Flash DED, the SYSCTL_DEDERRADDR can be used as is.

FLASH_ERR_05 *FLASH Module*

Category

Functional

Function

DEDERRADDR can have incorrect reset value

Description

The reset value of the SYSCTL->DEDERRADDR can return a 0x00C4013C instead of the correct 0x00000000. The location of the error is in the Factory Trim region and is not indicative of a failure, it can be properly ignored. The reset value tends to change once NONMAIN has been programmed on the device.

Workaround

Accept 0x00C4013C as another reset value, so the default value from boot can be 0x00000000 or 0x00C4013C. The return value is outside of the range of the MAIN flash on the device so there is no potential of this return coming from an actual FLASH DED status.

FLASH_ERR_08 *FLASH Module*

Category

Functional

Function

Hard fault isn't generated for typical invalid memory region

Description

Hard fault isn't generated while trying to access illegal memory address space as shown below: 1. 0x010053FF - 0x20000000 2. 0x40BFFFFFF - 0x41C00000 3. 0x41C007FF - 0x41C40000

Workaround

No

GPIO_ERR_03

GPIO Module

Category

Functional

Function

On a debugger read to GPIO EVENT0 IIDX, interrupt is cleared.

Description

EVENT0's IIDX of GPIO, on a debugger read is treated as a CPU read and interrupt is getting cleared.

Workaround

During the debug, the IIDX of event0 can be read by software reading RIS.

GPIO_ERR_04

GPIO Module

Category

Functional

Function

Configuring global fastwake is not allowing PAD data to go to DIN register

Description

When configuring the fast wake only bit in the CTL register and forcing data to PAD in run mode, the data in PAD is not reflected in the DIN register. This is because the CTL register configuration prevents any data from flowing from the PAD to the DIN register.

Workaround

Avoid using the GPIO fastwake-only function when expecting data on the PAD entering the DIN register.

I2C_ERR_04

I2C Module

Category

Functional

Function

When SCL is low and SDA is high the Target i2c is not able to release the stretch.

Description

- 1: SCL line grounded and released, device indefinitely pulls SCL low.
- 2: Post clock stretch, timeout, and release; if there is another clock low on the line, device indefinitely pulls SCL low.

Workaround

If the I2C target application does not require data reception in low power mode using Async fast clock request, disabling SWUEN by default is recommended, including during reset or power cycle. In this case, bug description 1 and 2 does not occur.

If the I2C target application requires data reception in low power mode using Async fast clock request, enable SWUEN just before entering low power and clear SWUEN after low power exit. Even in this scenario, bug description 1 and 2 can occur when the I2C target is in low power, it will indefinitely stretch the SCL line if there is a continuous clock stretching or timeout caused by another device on the bus. To recover from this situation, enable the low timeout interrupt on the I2C target device, reset and re-initialize the I2C module within the low timeout ISR.

I2C_ERR_05	I2C Module
Category	Functional
Function	I2C SDA can get stuck to zero if we toggle ACTIVE bit during ongoing transaction
Description	If ACTIVE bit is toggled during an ongoing transfer, the state machine will be reset. However, the SDA and SCL output which is driven by the controller will not get reset. There is a situation where SDA is 0 and the controller has gone into IDLE state, here the controller won't be able to move forward from the IDLE state or update the SDA value. The target's BUSBUSY is set (toggling of the ACTIVE bit is leading to a start being detected on the line) and the BUSBUSY won't be cleared as the controller will not be able to drive a STOP to clear it.
Workaround	Do not toggle the ACTIVE bit during an ongoing transaction.
I2C_ERR_06	I2C Module
Category	Functional
Function	SMBus High timeout feature fails at I2C clock less than 24KHz onwards
Description	SMBus High timeout feature is failing at I2C clock rate less than 24KHz onwards (20KHz, 10KHz). From SMBUS Spec, the upper limit on SCL high time during active transaction is 50us. Total time taken from writing of START MMR bit to SCL low is 60us, which is >50us. It will trigger the timeout event and let the I2C controller goes into IDLE without completing the transaction at the start of transfer itself. Below is detailed explanation. For SCL is configured as 20KHz, SCL low and high period is 30us and 20us respectively. First, START MMR bit write at the same time high timeout counter starts decrementing. Then, it takes one SCL low period (30us) from START MMR bit write to SDA goes low (start condition). Next, it takes another SCL low period (30us) from SDA goes low (start condition) to SCL goes low (data transfer starts) which should stop the high timeout counter at this point. As a total, it takes 60us from counter start to end. However, due to the upper limit(50us) of the high timeout counter, the timeout event will still be triggered although the I2C transaction is working fine without issue.
Workaround	Do not use SMBus High timeout feature when I2C clock is less than 24KHz onwards.
I2C_ERR_07	I2C Module
Category	Functional
Function	Back to back controller control register writes will cause I2C to not start.
Description	Back-to-Back CTR register writes will cause the next CTR.START to not properly cause the start condition.

I2C_ERR_07 (continued)

I2C Module

Workaround

Write all the CTR bits including CTR.START in a single write or wait one clock cycle between the CTR writes and CTR.START write.

I2C_ERR_08

I2C Module

Category

Functional

Function

FIFO Read directly after RXDONE interrupt causes erroneous data to be read

Description

When the RXDONE interrupt happens the FIFO is not always updated for the latest data.

Workaround

Wait 2 I2C CLK cycles for the FIFO to make sure to have the latest data. I2C CLK is based on the CLKSEL register in the I2C registers.

I2C_ERR_09

I2C Module

Category

Functional

Function

Start address match status might not be updated in time for a read through the ISR if running I2C at slow speeds.

Description

If running at I2C speeds less than 100kHz then the ADDRMATCH bit (address match in the TSR register) might not be set in time for the read through an interrupt.

Workaround

If running at below 100kHz on I2C, wait at least 1 I2C CLK cycle before reading the ADDRMATCH bit.

I2C_ERR_10

I2C Module

Category

Functional

Function

I2C Busy status is enabled preventing low power entry

Description

When in I2C Target mode, the I2C Busy Status stays high after a transaction if there is no STOP bit.

Workaround

Program the I2C controller to send the STOP bit and don't send a NACK for the last byte. Terminate any I2C transfer with a STOP condition to maintain proper BUSY status and asynchronous clock request behavior (for low power mode reentry).

I2C_ERR_13	<i>I2C Module</i>
Category	Functional
Function	Polling the I2C BUSY bit might not guarantee that the controller transfer has completed
Description	After setting the CCTR.BURSTRUN bit to initiate an I2C controller transfer, it takes approximately 3 I2C functional clock cycles for the BUSY status to be asserted. If polling for the BUSY bit is used immediately after setting CCTR.BURSTRUN to wait for transfer completion, the BUSY status might be checked before it is set. This problem is more likely to occur with high CLKDIV values (resulting in a slower I2C functional clock) or under higher compiler optimization levels.
Workaround	Add software delay before polling BUSY status. Software delay = $3 \times \text{CPU CLK} / \text{I2C functional clock}$ = $3 \times \text{CPU CLK} / (\text{CLKSEL} / \text{CLKDIV})$ For example, with a clock divider (CLKDIV) of 8, a clock source of 4 MHz(MFCLK), and CPU CLK of 32 MHz: Software delay = $3 \times 32 \text{ MHz} / (4 \text{ MHz} / 8) = 192 \text{ CPU cycles}$
KEYSTORE_ERR_01	<i>KEYSTORE Module</i>
Category	Functional
Function	STATUS.STAT value can be 0 or 1 without key access
Description	STATUS.STAT has a reset value of 1 and turns to 0 under these conditions: 1. After reset, debugger access via the register window returns 0x00. 2. After reset, the first CPU read returns 0x01, while subsequent CPU reads return 0x00. 3) After reset, first reading any other KEYSTORE register and then reading STATUS.STAT return 0x00.
Workaround	STATUS.STAT=0x0 means "No Error" . For checking if a slot is valid or not (Whether key is present), check STATUS.VALID.
MATHACL_ERR_01	<i>MATHACL Module</i>
Category	Functional
Function	MATHACL status error bit does not get cleared
Description	If there is a status error generated by the mathacl (ex. divide by 0), then the status register never gets cleared.
Workaround	Reset the peripheral to clear the status bit.

MATHACL_ERR_0

2

MATHACL Module

Category

Functional

Function

MATHACL COS(-180) gives 1 instead of -1, SIN(-90) will give 1 instead of -1

Description

MATHACL will return a 1 instead of a -1 when performing COS(-180) or SIN(-90)

Workaround

No workaround, make the result negative in software.

PMCU_ERR_09

PMCU Module

Category

Functional

Function

RSTCAUSE is updating incorrectly as 0xC, after a POR (NRST>1s) reset

Description

When using NRST to trigger POR (NRST>1s) reset, RSTCAUSE is updating incorrectly as 0xC, which is expected as 0x2.

Workaround

When need check reset cause, use one of the available SHUTDOWN memory bytes (SHUTDNSTOREx) to store a non-zero data after get RSTCAUSE status. When RSTCAUSE returns 0xC, then a POR occurs if the SHUTDNSTOREx data cleared, or a BOR occurs if the SHUTDNSTOREx data maintained.

PMCU_ERR_10

PMCU Module

Category

Functional

Function

VBOOST might have larger delay under certain operating conditions

Description

VBOOST for analog MUX has large delay at VDD<1.8V, which delays settling time of other modules like HFXT, COMP, SYSOSC(FCL-external R),OPA and GPAMP.

Workaround

Keep VDD>=1.8V and use VBOOST in ONALWAYS mode using GENCLKCFG[23:22]=0x2.

PMCU_ERR_11

PMCU Module

Category

Functional

Function

NRST<1sec pulse giving wrong rstcause in shutdown mode

PMCU_ERR_11

(continued)

PMCU Module

Description

The rstcause value is wrong under the following condition. Though the expected rstcause is 0x05.

- (i) Device is configured for shutdown mode
- (ii) WFI() is called
- (iii) Give NRST<1sec pulse to bring device out from shutdown mode

Workaround

No workaround.

RST_ERR_01

RST Module

Category

Functional

Function

NRST release doesn't get detected when LFCLK_IN is LFCLK source and LFCLK_IN gets disabled

Description

When LFCLK = LFCLK_IN and we disable the LFCLK_IN, then comes a corner scenario where NRST pulse edge detection is missed and the device doesn't come out of reset. This issue is seen if the NRST pulse width is below 608us. NRST pulse above 608us, the reset can appear normally.

Workaround

Keep the NRST pulse width higher than 608us to avoid this issue.

RTC_ERR_01

RTC Module

Category

Functional

Function

Some RTC Interrupts are not available in STANDBY1

Description

When in STANDBY1, the RTCRDY and RTC_PRESCALER1 interrupts cannot wakeup the device.

Workaround

When waking up the device from STANDBY1 with the RTC, use other available interrupts such as RTC_ALARM and RTC_PRESCALER0.

SPI_ERR_02

SPI Module

Category

Functional

Function

Missing SPI Clock and data bytes after wake-up from low power mode (LPM)

SPI_ERR_02

(continued)

Description

SPI Module

After device wake-up from a low power state, the SPI module can not properly propagate the first few clock cycles and data bits of the first byte sent out.

Workaround

To maintain SPI data integrity after a wakeup, use the following sequence when entering and exiting LPMs:

- 1.Disable SPI module
- 2.Wait for Interrupt(WFI)- enter LPM
- 3.Wake up from LPM (any source).
- 4.Enable the SPI module.

SPI_ERR_04

SPI Module

Category

Functional

Function

IDLE/BUSY status toggle after each frame receive when SPI peripheral is in only receive mode.

Description

In case of SPI peripheral in only receive mode, the IDLE interrupt and BUSY status are toggling after each frame receive while SPI is receiving data continuously(SPI_PHASE=1). Here there is no data loaded into peripheral TXFIFO and TXFIFO is empty.

Workaround

Do not use SPI peripheral only receive mode. Set SPI peripheral in transmit and receive mode. You do not need to set any data in the TX FIFO for SPI.

SPI_ERR_05

SPI Module

Category

Functional

Function

SPI Peripheral Receive Timeout interrupt is setting irrespective of RXFIFO data

Description

When using the SPI timeout interrupt the RXTIMEOUT can continue decrementing even after the final SPI CLK is received, which can cause a false RXTIMEOUT.

Workaround

Disable the RXTIMEOUT after the last packet is received (this can be done in the ISR) and re-enable when SPI communication starts again.

SPI_ERR_06

SPI Module

Category

Functional

SPI_ERR_06

(continued)

SPI Module**Function**

IDLE/BUSY status does not reflect the correct status of SPI IP when debug halt is asserted

Description

IDLE/BUSY is independent of halt, it is only gating the RXFIFO/TXFIFO writing/reading strobes. So, if controller is sending data, although it's not latched in FIFO but the BUSY is getting set. The POCI line transmits the previously transmitted data on the line during halt

Workaround

Don't use IDLE/BUSY status when SPI IP is halted.

SPI_ERR_07**SPI Module****Category**

Functional

Function

SPI underflow event may not generate if read/write to TXFIFO happen at the same time for SPI peripheral

Description

When SPI.CTL0.SPH = 0 and the device is configured as the SPI peripheral.

If there is a write to the TXFIFO WHILE there is a read request from the SPI controller, then an underflow event may not be generated as the read/write request is happening simultaneously.

Workaround

Ensure the TXFIFO is not empty when the SPI Controller is addressing the device, this can be done by preloading data to avoid a write and read to the same TXFIFO address. Alternatively, data checking strategies, like CRC, can be used to verify the packets were sent properly, then the data can be resent if the CRC doesn't match.

SRAM_ERR_03**SRAM Module****Category**

Functional

Function

SRAM Parity and ECC function is not supported on Rev A devices

Description

SRAM Parity and ECC function is not supported on Rev A devices. Please do not use SRAM Parity and ECC function on Rev A devices.

Workaround

None.

SYSCTL_ERR_01**SYSCTL Module****Category**

Functional

SYSCTL_ERR_01

(continued)

SYSCTL Module

Function

SW-POR functionality is combined with HW-POR

Description

When a user writes to the LFSSRST register with the correct key to generate a software-triggered POR, the RSTCAUSE register will display 0x2 (indicating an NRST-triggered POR) instead of the expected 0x3 (Software-Triggered POR). This occurs because the SW-POR functionality is combined with the HW-POR path.

Workaround

No

SYSCTL_ERR_02 **SYSCTL Module**

Category

Functional

Function

SYSSTATUS.FLASHSEC is non-zero after a BOOTRST

Description

After BOOTRST/ bootcode completion SYSSTATUS.FLASHSEC is non-zero. This the customer will see after bootcode completion.

Workaround

No

SYSCTL_ERR_03 *SYSCTL Module*

Category

Functional

Function
DEDERRADDR persists after a SYSRESET or a write to the SYSSTATUSCLR
Details

DEDERRADDR persists after either a SYSRESET or a write to the SYSSTATUSCLR register. Its value is overwritten only when a new FLASHDED error occurs. This behavior contradicts the Technical Reference Manual (TRM), which specifies its initial reset value as zero.

Workaround

No workaround

SYSCTL_ERR_04 *SYSCTL Module*

Category

Functional

Function

SYSSTATUS.FLASHSEC is not cleared after a SYSRESET

Description

SYSSTATUS.FLASHSEC is not cleared after a SYSRESET and is only cleared by writing to the SYSSTATUSCLR register.

Workaround

No

SYSOSC_ERR_01 *SYSOSC Module*

Category

Functional

Function

MFCLK drift when using SYSOSC FCL together with STOP1 mode

Description

If MFCLK is enabled AND SYSOSC is using the frequency correction loop (FCL) mode AND STOP1 low power operating mode is used, then the MFCLK may drift by two cycles when SYSOSC shifts from 4MHz back to 32MHz (either upon exit from STOP1 to RUN mode or upon an asynchronous fast clock request that forces SYSOSC to 32MHz).

Workaround

Use STOP0 mode instead of STOP1 mode, there is no MFCLK drift when STOP0 mode is used.

OR

Do not use SYSOSC in the FCL mode (leave FCL disabled) when using STOP1.

SYSOSC_ERR_02 ***SYSOSC Module***

Category

Functional

Function

MFCLK does not work when Async clock request is received in an LPM where SYSOSC was disabled in FCL mode

Description

MFCLK will not start to toggle in below scenario:

1. FCL mode is enabled and then MFCLK is enabled
2. Enter a low power mode where SYSOSC is disabled (SLEEP2/STOP2/STANDBY0/STANDBY1).
3. Async request is received from some peripherals which use MFCLK as functional clock. On receiving async request, SYSOSC gets enabled and ulpclk becomes 32MHz. But MFCLK is gated off and it does not toggle at all as the device is still set to the LPM.

Workaround

If SYSOSC is using the FCL mode - Do not enable the MFCLK for a peripheral when you're entering a LPM mode which would typically turn off the SYSOSC.

SYSPLL_ERR_01 ***SYSPLL Module***

Category

Functional

Function

SYSPLL Frequency may not lock to correct frequency when enabled.

Description

When setting the SYSPLLEN bit to 1 in SYSCTL HSCLKEN register, the SYSPLL will run the phase locked loop search. The search can potentially fail where the frequency will not be set to the correct value, instead the resultant frequency will be drastically different than the configured frequency.

Workaround

Check the frequency output of the SYSPLL using the Frequency Clock Counter (FCC) anytime the SYSPLLEN bit is set to 1. Once the frequency is correct it will maintain the correct value until disabled and reenabled (SYSPLLEN set to 0 then 1), once reenabled the PLL will re-run the search and the SYSPLL output will need to be rechecked.

Workaround 1: Set FCC with SYSPLLCLK0 as the CLK input and LFCLK as the Trigger source. Run the FCC and check the value for the configured SYSPLL frequency with reference to the LFCLK; for example, with SYSPLL = 80MHz and LFCLK = 32kHz, the resultant FCC count should be $80,000,000/32,768 = \sim 2441$. The count will vary depending on the combined clock accuracies, so it is recommended to add a +5% to allowed range. Estimated time for FCC is 30us.

FCC Settings: SYSCTL.GENCLKCFG.FCCTRIGCNT = 0,
SYSCTL.GENCLKCFG.FCCTRIGSRC = 1, SYSCTL.GENCLKCFG.FCCSELCLK = 4;

If the FCC value is incorrect, disable and reenable the SYSPLL by setting SYSPLLEN to 0 then 1. Rerun the FCC check.

Workaround 2: Output SYSOSC/2 from the CLK_OUT pin and route the signal into FCC_IN. Use the SYSPLLCLK0 as the FCC CLK and the FCC_IN for the trigger

SYSPLL_ERR_01 (continued)

SYSPLL Module

source. Run the FCC for 16 Clock cycles, and check the value for the configured SYSPLL frequency with reference to the SYSOSC; for example, with SYSPLL = 80MHz and SYSOSC/2 = 16MHz, the resultant FCC count should be $80,000,000/16,000,000 * 16 = \sim 80$. The count will vary depending on the combined clock accuracies, so it is recommended to add a +5% to allowed range. Estimated time for FCC is 1us.

FCC Settings: SYSCTL.GENCLKCFG.FCCTRIGCNT = 0x0F,
SYSCTL.GENCLKCFG.FCCTRIGSRC = 0, SYSCTL.GENCLKCFG.FCCSELCLK = 4;

If the FCC value is incorrect, disable and reenable the SYSPLL by setting SYSPLEN to 0 then 1. Rerun the FCC check.

TIMER_ERR_04

TIMER Module

Category

Functional

Function

TIMER re-enable may be missed if done close to zero event

Description

When using a TIMER in one shot mode, TIMER re-enable may be missed if done close to zero event. The HW update to the timer enable bit will take a single functional clock cycle. For example, if the timer's clock source is 32.768kHz and clock divider of 3, then it will take ~100us to have the enable bit set to 0 properly.

Workaround

Wait 1 functional clock cycle before re-enabling the timer OR the timer can be disabled first before re-enabling.

Disable the counter with CTRCTL.EN = 0, then reenable with CTRCTL.EN = 1

TIMER_ERR_06

TIMA and TIMG Module

Category

Functional

Function

Writing 0 to CLKEN bit does not disable counter

Description

Writing 0 to the Counter Clock Control Register(CCLKCTL) Clock Enable bit(CLKEN) does not stop the timer.

Workaround

Stop the timer by writing 0 to the Counter Control(CTRCTL) Enable(EN) bit.

TIMER_ERR_07

Initial repeat counter has 1 less period than next repeats Module

Category

Functional

TIMER_ERR_07

(continued)

Initial repeat counter has 1 less period than next repeats Module

Function

TIMER

Description

When using the timer repeat counter mode, the first repeat will have 1 less count than the subsequent repeats because the following repeat counters will include the transition between 0 and the load value. For example if the TIMx.RCLD = 0x3 then 3 observable zero events would appear on the first repeat counter and 4 observable zero events would appear on the following repeat counter sequences.

Workaround

Set the initial RCLD value to 1 more than the expected RCLD, then in the ISR for the Repeat Counter Zero Event (REPC), set the RCLD to the intended RCLD value. For example, if intending to have 4 repeats, set the initial RCLD value to RCLD = 0x5, then in the timer ISR for the REPC interrupt, set RCLD = 0x4. Now all timer repeats will have the same number of zero/load events.

UART_ERR_01

UART Module

Category

Functional

Function

UART start condition not detected when transitioning to STANDBY1 Mode

Description

After servicing an asynchronous fast clock request that was initiated by a UART transmission while the device was in STANDBY1 mode, the device will return to STANDBY1 mode. If another UART transmission begins during the transition back to STANDBY1 mode, the data is not correctly detected and received by the device.

Workaround

Use STANDBY0 mode or higher low power mode when expecting repeated UART start conditions.

UART_ERR_02

UART Module

Category

Functional

Function

UART End of Transmission interrupt not set when only TXE is enabled

Description

UART End Of Transmission (EOT) interrupt does not trigger when the device is set for transmit only (CTL0.TXE = 1, CTL0.RXE = 0). EOT successfully triggers when device is set for transmit and receive (CTL0.TXE = 1, CTL0.RXE = 1)

Workaround

Set both CTL0.TXE and CTL0.RXE bits when utilizing the UART end of transmission interrupt. Note that you do not need to assign a pin as UART receive.

UART_ERR_04 *UART Module*

Category

Functional

Function

Incorrect UART data received with the fast clock request is disabled when clock transitions from SYSOSC to LFOSC

Description

Scenario:

1. LFCLK selected as functional clock for UART
2. Baud rate of 9600 configured with 3x oversampling
3. UART fast clock request has been disabled

If the ULPCLK changes from SYSOSC to LFOSC in the middle of a UART RX transfer, it is observed that one bit is read incorrectly

Workaround

Enable UART fast clock request while using UART in LPM modes.

UART_ERR_05 *UART Module*

Category

Functional

Function

Limitation of debug halt feature in UART module

Description

All Tx FIFO elements are sent out before the communication comes to a halt against the expectation of completing the existing frame and halt.

Workaround

Please make sure data is not written into the TX FIFO after debug halt is asserted.

UART_ERR_06 *UART Module*

Category

Functional

Function

Unexpected behavior RTOUT/Busy/Async in UART 9-bit mode

Description

UART receive timeout (RTOUT) is not working correctly in multi node scenario, where one UART will act as controller and other UART nodes as peripherals, each peripheral is configured with different address in 9-bit UART mode.

First UART controller communicated with UART peripheral1, by sending peripheral1's address as a first byte and then data, peripheral1 has seen the address match and received the data. Once controller is done with peripheral1, peripheral1 is not setting the RTOUT after the configured timeout period, if controller immediately starts the communication with another UART peripheral (peripheral2) which is configured with different address on the bus. The peripheral1 RTOUT counter is resetting while communication ongoing with peripheral2 and peripheral1 setting its RTOUT only after UART controller is completed the communication with peripheral2.

Similar behavior observed with BUSY and Async request. Busy and Async request

UART_ERR_06 (continued)

UART Module

is setting even if address does not match while controller communicating with other peripheral on the bus.

Workaround

Do not use RTOUT/ BUSY /Async clock request behavior in multi node UART communication where single controller is tied to multiple peripherals.

UART_ERR_07

UART Module

Category

Functional

Function

RTOUT counter not counting as per expectation in IDLE LINE MODE

Description

In IDLE LINE MODE in UART, RTOUT counter gets stuck, even when the line is IDLE and FIFO has some elements. This means that RTOUT interrupts will not work in IDLE LINE MODE.
In case of an address mismatch, RTOUT counter is reloaded when it sees toggles on the Rx line.
In case of a multi-responder scenario this could lead to an indefinite delay in getting an RTOUT event when communication is happening between the commander and some other responder.

Workaround

Do not enable RTOUT feature when UART module is used either in IDLELINE mode/ multi-node UART application.

UART_ERR_08

UART Module

Category

Functional

Function

STAT BUSY does not represent the correct status of UART module

Description

STAT BUSY is staying high even if UART module is disabled and there is data available in TXFIFO.

Workaround

Poll TXFIFO status and the CTL0.ENABLE register bit to identify BUSY status.

UART_ERR_10

UART Module

Category

Functional

Function

BUSY bit setting is delayed for UART IrDA mode

UART_ERR_10

(continued)

UART Module

Description

In IrDA mode, the UART.STAT.BUSY bit is set on the second edge of the IrDA start pulse; which means a whole bit transmission would complete before the BUSY status is properly set. During this time if the software polls the BUSY bit, an incorrect indication of UART not being busy would be observed even when the IrDA start pulse is ongoing. BUSY status will be influenced by the baud rate of the UART, the slower the UART transmission the longer time before BUSY is properly set.

Workaround

Delay for the length of a bit transmission before checking the BUSY status. Alternatively, checking for UART.STAT.BUSY == 0x0, then UART.STAT.BUSY == 0x1, is another workaround to make a dynamic delay independent of baud rate or other ISRs.

UART_ERR_11

UART Module

Category

Functional

Function

UART Receive timeout starts counting earlier than expected during the STOP bit transaction

Description

During the STOP bit transaction the Receive timeout will start counting in the middle of the STOP bit transaction, which can cause an unintended RTOUT interrupt if the RXTOSEL setting is too small. For example, if the baud rate was 1Mbps, and RXTOSEL was set to 1, the expected RTOUT should happen 1us after the STOP bit transaction, instead the RTOUT interrupt is getting set at 0.5 us.

Workaround

The UART.IFLS.RXTOSEL register selects the bit time before the Receive Time out (RTOUT) interrupt will fire. The RXTOSEL value needs to be greater than 1 in order to prevent an early interrupt. The receive timeout time can be calculated as: Receive timeout = (RXTOSEL - 0.5) / Baud Rate

7 Trademarks

All trademarks are the property of their respective owners.

8 Revision History

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

Changes from July 30, 2025 to November 30, 2025 (from Revision B (July 2025) to Revision C (November 2025))

Page

• Removed PMCU_ERR_12.....	1
• ADC_ERR_06 Module was updated.....	5
• ADC_ERR_06 Function was updated.....	5
• ADC_ERR_06 Workaround was updated.....	5
• ADC_ERR_06 Description was updated.....	5
• ADC_ERR_10 Description was updated.....	5
• ADC_ERR_10 Workaround was updated.....	5
• CPU_ERR_02 Function was updated.....	6
• CPU_ERR_02 Workaround was updated.....	6

• CPU_ERR_03 Function was updated.....	6
• CPU_ERR_03 Description was updated.....	6
• CPU_ERR_03 Workaround was updated.....	6
• FLASH_ERR_08 Module was updated.....	8
• FLASH_ERR_08 Function was updated.....	8
• FLASH_ERR_08 Description was updated.....	8
• FLASH_ERR_08 Workaround was updated.....	8
• I2C_ERR_07 Workaround was updated.....	10
• I2C_ERR_09 Description was updated.....	11
• I2C_ERR_09 Workaround was updated.....	11
• I2C_ERR_13 Category was updated.....	12
• I2C_ERR_13 Module was updated.....	12
• I2C_ERR_13 Function was updated.....	12
• I2C_ERR_13 Workaround was updated.....	12
• I2C_ERR_13 Description was updated.....	12
• KEYSTORE_ERR_01 Module was updated.....	12
• KEYSTORE_ERR_01 Function was updated.....	12
• KEYSTORE_ERR_01 Description was updated.....	12
• KEYSTORE_ERR_01 Workaround was updated.....	12
• SPI_ERR_07 Description was updated.....	16
• SPI_ERR_07 Workaround was updated.....	16
• SYSCTL_ERR_01 Module was updated.....	16
• SYSCTL_ERR_01 Function was updated.....	16
• SYSCTL_ERR_01 Description was updated.....	16
• SYSCTL_ERR_01 Workaround was updated.....	16
• SYSCTL_ERR_02 Module was updated.....	17
• SYSCTL_ERR_02 Function was updated.....	17
• SYSCTL_ERR_02 Description was updated.....	17
• SYSCTL_ERR_02 Workaround was updated.....	17
• SYSCTL_ERR_04 Workaround was updated.....	18
• SYSCTL_ERR_04 Module was updated.....	18
• SYSCTL_ERR_04 Function was updated.....	18
• SYSCTL_ERR_04 Description was updated.....	18
• SYSPLL_ERR_01 Category was updated.....	19
• SYSPLL_ERR_01 Module was updated.....	19
• SYSPLL_ERR_01 Function was updated.....	19
• SYSPLL_ERR_01 Description was updated.....	19
• SYSPLL_ERR_01 Workaround was updated.....	19
• TIMER_ERR_04 Description was updated.....	20
• TIMER_ERR_04 Workaround was updated.....	20
• TIMER_ERR_07 Category was updated.....	20
• TIMER_ERR_07 Module was updated.....	20
• TIMER_ERR_07 Description was updated.....	20
• TIMER_ERR_07 Workaround was updated.....	20
• TIMER_ERR_07 Function was updated.....	20
• UART_ERR_10 Module was updated.....	23
• UART_ERR_10 Function was updated.....	23
• UART_ERR_10 Description was updated.....	23
• UART_ERR_10 Workaround was updated.....	23
• UART_ERR_11 Module was updated.....	24
• UART_ERR_11 Function was updated.....	24
• UART_ERR_11 Description was updated.....	24
• UART_ERR_11 Workaround was updated.....	24

IMPORTANT NOTICE AND DISCLAIMER

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, regulatory or other requirements.

These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you fully indemnify TI and its representatives against any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to [TI's Terms of Sale](#), [TI's General Quality Guidelines](#), or other applicable terms available either on [ti.com](#) or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products. Unless TI explicitly designates a product as custom or customer-specified, TI products are standard, catalog, general purpose devices.

TI objects to and rejects any additional or different terms you may propose.

Copyright © 2025, Texas Instruments Incorporated

Last updated 10/2025